Serial No.: 09/408,430

Filed: September 29, 1999

Attorney Case No.: EMC2-033PUS (Formerly 07072/087001)

<u>REMARKS</u>

The specification has been amended to make the text agree with FIG. 9 and the description of the operation of the circuit on page 28.

The Examiner is respectfully invited to telephone the undersigning attorney regarding this amendment or this application.

The Assistant Commissioner is hereby authorized to charge payment of any additional fees associated with this communication or credit any overpayment to Deposit Account No. 50-0845.

Respectfully submitted,

Date

Richard M./Sharkansky

Attorney for Applicant(s) Registration No. 25,800

Daly, Crowley & Mofford, LLP

275 Turnpike Street, Suite 101

Canton, MA 02021-2310 Telephone (781) 401-9988 x23

Facsimile (781) 401-9966

Attachment: Sheet with markings showing changes made

Serial No.: 09/408,430 Filed: September 29, 1999

Attorney Case No.: EMC2-033PUS (Formerly 07072/087001)

Version of Specification With Markings To Show Changes

Referring now to FIG. 9, a circuit 400 is shown for detecting a hard fault (i.e., a ground fault or a connection to a fixed, unchanging voltage) on a bi-directional data line 402. The circuit 400 includes an input/output terminal 304 connected to one end of the bi-directional line 402; a data receiver 406 having an input coupled to a second end of the bi-directional line 402 for receiving data on the terminal 404; an data driver 408 having an output coupled to second end of the bi-directional line 402 for producing data on the terminal 404; an XOR gate 410 having a pair of inputs, one being coupled to an <u>inputoutput</u> of the data driver 408 and the other being coupled to an <u>inputoutput</u> of the data receiver 408, for determining whether data produced by the data driver is received by the data receiver.

1